

CLASSIFICATION

SECRET

SECURITY INFORMATION

CENTRAL INTELLIGENCE AGENCY

REPORT NO. CD NO.

COUNTRY INFORMATION REPORT

COUNTRY East Germany

DATE DISTR 22 September 1953

SUBJECT Condition of East German Coal Mines

NO. OF PAGES 3

PLACE ACQUIRED

NO. OF ENCLS.

ELISTED BELOW

DATE OF INFO. SUPPLEMENT TO
REPORT NO

25X1A

This document contains information relating to the national defense of the United States within the meaning of the Espionage Act of 1917, U.S.C., §§ 7 and 18, as amended. Its transmission or the revelation of the contents in any manner to an unauthorized person is prohibited by law. Reproduction of this form is prohibited.

THIS IS UNEVALUATED INFORMATION

25X1X

SOURCE:

1. Many of the coal mine shafts of East German coal mines are becoming unfit to work in, due to the dangerous conditions resulting from insufficient or faulty shoring timbers and supports. This situation has been impeding work for some time and is only now becoming critical. Many attempts have been made to obtain the necessary materials through East-West trade, since they are unavailable in East Germany; recently an attempt was made to obtain pitch pine from the U. S. through the Swiss firm of Eximimport.
2. In the Steinkohlenbergbau in Zwickau, the inspecting safety commission recently refused to certify most of the shafts as safe, and the workers refuse to enter many of the shafts. In all the coal mines of East Germany, an estimated one-third of the shafts are not being worked because of refusal of the miners to work in them.

25X1A

CLASSIFICATION: SECRET

STATE	<input checked="" type="checkbox"/> NAVY	<input checked="" type="checkbox"/> AIR	<input checked="" type="checkbox"/> NSRB	<input checked="" type="checkbox"/> FBI	DISTRIBUTION	OIT	<input checked="" type="checkbox"/>
ASIA							